## ELECTRICAL SYMBOLS - DIAGRAM

DELTA CONNECTION

MOTOR, SINGLE-PHASE

MOTOR, THREE-PHASE

TRANSFORMER

WYE CONNECTION

EARTH GROUND

JUNCTION BOX

PB PULL BOX

— SWITCH, MULTIPOSITION

- SWITCH, SINGLE BREAK

★ NORMALLY CLOSED RELAY CONTACT

+ NORMALLY OPEN RELAY CONTACT

CIRCUIT BREAKER

DRAWOUT AIR CIRCUIT BREAKER

RELAY; NUMBER INDICATES RELAY TYPE

50 = INSTANTANEOUS OVERCURRENT OR RATE-OF-RISE

51 = AC-TIME OVERCURRENT

67 = AC-DIRECTIONAL OVERCURRENT

86 = LOCKING OUT



DETAIL TITLE / ELECTRICAL SYMBOLS - DIAGRAM

SCALE: NONE

DATE ISSUED: JULY 1, 2020 CAD DETAIL NO.: SD260511-07 DWG