

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

January 1, 2024

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

May 1, 2022

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Five pound opening force requirement added for doors with closers in accordance with ABAAS criteria. ABAAS added under Application Publications. Test data record added under submittal requirements. Language added to properly adjust closer for maximum opening force at time of installation.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

May 1, 2022

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

April 1, 2022

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Continuous hinges were removed from the following hardware sets when used on fire rated doors: 1E, 1J, 3H, 4D, 4F, 5B, 5F, 10B, 11B, E3, and SH-3C

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

April 1, 2022

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

January 1, 2021

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Activation pressure for Ligature Resistant Door Alarm was modified from 1lb to 5lbs minimum.
2. Added a spec section for Card Reader Controlled Electric Locks.
3. Hardware sets R1, R1A and R7A modified to provide more information for required components of the specified Guestroom Lock.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

January 1, 2021

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

April 1, 2020

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Update referenced standards and formatting.
2. Corrected publication dates.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

April 1, 2020

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

January 1, 2020

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. All references to UFAS, the Uniform Federal Accessible Standards have been removed and the section has been updated to reference ABAAS, the Architectural Barriers Act Accessible Standard.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

January 1, 2020

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

November 1, 2019

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Correction provided on Hardware Sets where lockset F08 was identified as a classroom lock. Correction made so that classroom locks are identified as BHMA lockset F05

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

November 1, 2019

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

October 1, 2019

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Privacy locksets within the Spec. section's hardware sets that contained thumbturns on the outside of the lockset have been removed for patient privacy concerns

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

October 1, 2019

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

August 1, 2019

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. The requirement for maintaining power to the control panel of the ligature resistant alarm system has been changed to require a dedicated battery backup system and an emergency power feed for maintaining power to the control panel in the event of a power failure due to a power outage (Article 2.19, Paragraph B, subparagraph 7.a).

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

August 1, 2019

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

May 1, 2019

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. An optional paragraph 2.19 Ligature Resistant Door Alarm was added for where Mental Healthcare and Behavioral services are provided.
2. Ligature Resistant Door Alarms were added to the following hardware sets; MH1, MH4, MH5, and MH6.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

May 1, 2019

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

January 1, 2016

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Requirements for Anti-ligature alarm hardware were added for utilization on projects where Mental and Behavioral Health services are provided.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

January 1, 2016

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

February 1, 2015

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Adjusted hardware set HW-7B to include missing hardware items
2. Corrected spec. section reference at hardware set HW-13
3. At hardware sets HW-G1 thru HW-G10 reference to spec. section referenced was corrected.
4. Requirements for door pulls with plates and push plates has been updated.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

February 1, 2015

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

November 1, 2014

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Corrections made to ANSI/BHMA publication references in body of spec.
2. Two ANSI/BHMA publications added: A156.11-14 Cabinet Locks & A156.36 Auxiliary Locks
3. ANSI/BHMA publication A156.5 publication title updated to "Cylinders and Input Devices for Locks"

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

November 1, 2014

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

September 1, 2014

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Under Article 2.2, Continuous Hinges, at subparagraph 2 under paragraph C the option for aluminum as a base metal for interior hinges has been deleted.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION:

September 1, 2014

TITLE OF DOCUMENT:

Door Hardware, 08 71 00

DATE OF VERSION BEING SUPERSEDED (old):

December 1, 2013

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Referenced publication ANSI/BHMA A156.5 updated to reflect change in content of hardware devices represented in publication. Name of publication changed to reflect this change.
2. At Article 2.10, referenced ANSI/BHMA publication changed from A156.13 to A156.5 to reference correct publication.

Summary of Modifications/Changes in this Update

This Summary of Changes is for information only.
It is not a part of the referenced document, and should not be used for project documentation.

U.S. Department of Veterans Affairs ♦ Office of Construction & Facilities Management

DATE OF THIS VERSION (new)

December 1, 2013

TITLE OF DOCUMENT (new title if applicable):

[Click here to enter text.](#)

DATE OF VERSION BEING SUPERSEDED (old):

March 1, 2012

DESCRIPTION OF DOCUMENT (previous title, number, other identifying data):

Door Hardware, 08 71 00

SUMMARY OF CHANGES IN THIS VERSION:

1. Hardware Sets 1F, 1L, 1Q & 1R previous had a latchset F01. This update changes the latchset designation to F04 for these Hardware Sets. This change reflects a change in locksets for Exam Rooms from passage latchset to office lockset for greater privacy for patients